

**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NAOCE
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)
3. Incident Details
i. Date of Incident: 17/11/2015 ii. Date first reported: 17/11/2015
iii. Date of first investigation: 17/11/2015 iv. Spill Incidence No. 2015/SAR/274
v. Date of follow-up investigation:
vi. Time investigation started: 10:26 HOURS
vii. Estimated quantity spilled(bbls): 0.01 viii. Quantity Recovered:
4. Site Details
i. Site/Location: 18" TERIDABA / BRASS PIL AT OYEREGBENE
ii. State: BAYELSA iii. L.G.A: SILGA
iv. Spill Co-ordinates: N(m) NO 4° 29' 45" - 4"
E(m) EO 6° 04' 36" - 9"
v. Spill area
☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify)
vi. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify)
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)
iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify)
iv. Cause Of Spill.
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify)
v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (specify)



1. **Properties impacted by the incident**

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. **Nature of impact**

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. **Delineation of impacted area**

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. **Type of properties/ structures, if any, found outside the right-of-way**

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing net ☐ Makeshift
☐ Permanent ☐ Others

8. **Extent of Impact**

a) **Community** (indicate name)

- i.
 ii.
 iii.
 iv.

b) **Land** (indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) **Creeks/Creek lets** ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) **Swamp** ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) **River** ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) **Shoreline/water**

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken.....

11. Investigation carried out by

☐ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation. PREVIOUSLY REPAIRED CONE WAS CUT
OFF BY UNKNOWN PERSON FOR OIL THEFT ACTIVITIES.
INCREASE SURVEILLANCE FOR PREVENT FUTURE INCIDENT

13. Time investigation ended 11:15 HOURS

14. Name and Signature of Participants