

PHOTOGRAPHS TAKEN DURING JIV



Fig A: Spill point just before excavation



Fig B: Spill point after excavation



Fig C: Wrapping/Tape coating of incident facility



Fig D: Backfill after repair of incident facility



SPILL POINT