




NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY JOINT INVESTIGATION VISIT (JIV) FORM

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: N A O C
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
i. Date of Incident: 28 / 11 / 2015 ii. Date first reported: 28 / 11 / 2015
iii. Date of first investigation: 28 / 11 / 2015 iv. Spill Incidence No: 2015/SAR/293
v. Date of follow-up investigation:
vi. Time investigation started: 13 06 HRS
vii. Estimated quantity spilled(bbls): NIL viii. Quantity Recovered:
4. Site Details
i. Site/Location: 10" CLOUGH CREEK / TEBIABA P/L AT GBARAWU
ii. State: iii. L.G.A:
iv. Spill Co-ordinates: N(m) N 04° 44' 55.6"
E(m) E 005° 49' 26.0"
v. Spill area
☐ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
vi. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)
- iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify)
- iv. Cause Of Spill.
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....
- v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (specify).....



i. **Properties impacted by the incident**

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify)..... NIL

ii. **Nature of impact**

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. **Delineation of impacted area**

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. **Type of properties/ structures, if any, found outside the right-of-way**

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing net ☐ Makeshift
☐ Permanent ☐ Others

8. **Extent of Impact**

a) **Community** (indicate name)

- i.
 ii.
 iii.
 iv.

b) **Land** (indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) **Creeks/Creek lets**

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) **Swamp**

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) **River**

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) **Shoreline/water**

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. **Photograph/Map/Chart Ref.**

☒ Still photographs ☐ Video coverage ☐ Mapping

10. **Samples taken**.....

11. **Investigation carried out by**

☐ Foot ☒ Boat ☐ Aircraft

12. **Remarks/Recommendation**.....

.....

.....