



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NIGERIAN AGIP OIL COMPANY

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....

3. Incident Details

- i. Date of Incident: 03/01/16 ii. Date first reported: 03/01/16
iii. Date of first investigation: 03/01/16 iv. Spill Incidence No.: 2016/SAR/003
v. Date of follow-up investigation: -/-/-
vi. Time investigation started: 1052 HRS
vii. Estimated quantity spilled(bbls): NIL viii. Quantity Recovered: N/A

4. Site Details

- i. Site/Location: 18" TEBIDABA/BRASS P/L @ OYEREGBE
ii. State: BAYELSA iii. L.G.A.: SILGA
iv. Spill Co-ordinates: N(m) 04° 29' 20.8"
E(m) 006° 05' 05.8"

v. Spill area

- ☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....

vi. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☒ Others (specify)..... N/A

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock

ii. Type of Oil contaminant

- ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☒ Others (specify)..... NONE

iii. Facility

- ☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....

iv. Cause Of Spill.

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (specify).....

6. Impact of Incident

i. Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☒ Others (specify)..... NONE

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☒ Others..... N/A

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing net ☐ Makeshift
☐ Permanent ☒ Others N/A

8. Extent of Impact

a) Community (indicate name)

- i.
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken..... N/A

11. Investigation carried out by

☐ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation. A PREVIOUSLY WELDED
POINT WAS RE-ENTERED FOR
OIL THEFT ACTIVITIES.