



# NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY JOINT INVESTIGATION VISIT (JIV) FORM

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NIGERIAN AGIP OIL COMPANY

2. Type of Complaint/Incident:

☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution  
☐ Others (Specify).....

3. Incident Details

i. Date of Incident: 14/12/2015

ii. Date first reported: 14/12/2015

iii. Date of first investigation: 14/12/2015

iv. Spill Incidence No: 2015/SAR/802

v. Date of follow-up investigation:...../...../.....

vi. Time investigation started: 11:55 HRS

vii. Estimated quantity spilled(bbls): NIL

viii. Quantity Recovered: N/A

4. Site Details

i. Site/Location: 18" TIBIDABA/BRASS P/L @ OYEREBENE

ii. State: BAYELSA

iii. L.G.A: SOUTHERN ITAW

iv. Spill Co-ordinates: N(m) 04° 29' 30.8"  
E(m) 066° 05' 05.0"

v. Spill area

☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline

☐ Near shore ☐ Offshore ☐ Others (specify).....

vi. Structural Controls in Place

☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock  
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock

ii. Type of Oil contaminant

☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products

☐ Others (specify) NIL

iii. Facility

☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig  
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....

iv. Cause Of Spill.

☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident

☐ Operational Error ☐ Others (specify).....

v. Visible Sign of Third Party Interference

☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid

☐ Others (specify).....

## 6. Impact of Incident

### i. Properties impacted by the incident

- ☒ Farmland  
 ☒ Fish Pond  
 ☒ Vegetation  
 ☒ Fishing Net  
 ☒ Surface water  
☒ Venerable Objects  
☒ Others (specify).....

### ii. Nature of impact

- ☒ Oil stained vegetation  
 ☒ Oil stained fishing nets  
 ☒ Dead floating fishes  
☒ Dead floating crabs  
☒ Withering of vegetation  
☒ Others.....

### iii. Delineation of impacted area

- ☒ Within Company's facility/ROW  
☒ Outside Company's facility/ROW

## 7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops  
☒ Fish Farm/ Pond  
☒ Fishing net  
☒ Makeshift  
☒ Permanent  
☒ Others .....

## 8. Extent of Impact

### a) Community (indicate name)

- i. ....  
 ii. *N/A*  
 iii. ....  
 iv. ....

### b) Land (indicate area in m<sup>2</sup>)

- i. ....  
 ii. *N/A*  
 iii. ....  
 iv. ....

### b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      | <i>/</i>           | <i>/</i>        |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### c) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      | <i>/</i>           | <i>/</i>        |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### d) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      | <i>/</i>           | <i>/</i>        |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### e) Shoreline/water

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      | <i>/</i>           | <i>/</i>        |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

9. Photograph/Map/Chart Ref.

☒ Still photographs    ☐ Video coverage    ☐ Mapping

10. Samples taken.....

11. Investigation carried out by

☒ Foot    ☒ Boat    ☒ Aircraft

12. Remarks/Recommendation AGIP SHOULD INTENSIFY  
SURVEILLANCE ON THEIR FACILITY