

SOME PHOTOGRAPHS TAKEN DURING THE JIV



Fig A: The Leak point just before excavation



Fig B: Incident Facility



Fig C: Incident Facility during repair



Fig D: Patch Welding



Fig E: The Spill Point after repair



Fig F: Backfill after repair of incident facility