

SOME PHOTOGRAPHS TAKEN DURING THE JIV



Fig A: Spill point just before excavation



Fig B: The leak point after excavation



Fig C: Spill point covered with a cone



Fig D: The Spill Point after repair



Fig E: Backfill after repair of incident facility