

SOME PHOTOGRAPHS TAKEN DURING THE JIV



Fig A: Spill point just before excavation




Fig B: Spill point after excavation



Fig C: Oil spill impacted area



Fig D: Absorbent booms deployed to prevent further spread of crude oil



Fig E: The Leak Point Patch Welded



Fig F: Wrapping/Tape coating of incident facility