



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY JOINT INVESTIGATION VISIT (JIV) FORM

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NIGERIAN AGIP OIL COMPANY

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☐ Others (Specify).....

3. Incident Details

- i. Date of Incident: 28/03/2016 ii. Date first reported: 28/03/2016
iii. Date of first investigation: 12/04/2016 iv. Spill Incidence No: 2016/LAR/030/088
v. Date of follow-up investigation:
vi. Time investigation started: 1500HRS
vii. Estimated quantity spilled(bbls): 2.67 viii. Quantity Recovered: NIL

4. Site Details

- i. Site/Location: IDU 3S FLOWLINE AT WELLHEAD
ii. State: BAYELSA iii. L.G.A: YENEGOA
iv. Spill Co-ordinates: N(m) 05° 15' 54.3"
E(m) 006° 32' 50.9"
v. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (specify).....
vi. Structural Controls in Place
☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock

ii. Type of Oil contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify).....

iii. Facility

- ☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....

iv. Cause Of Spill.

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (specify).....

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (specify).....



1. Properties impacted by the incident
☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☐ Surface water
☒ Venerable Objects ☒ Others (specify).....
- ii. Nature of impact
☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
☒ Dead floating crabs ☒ Withering of vegetation ☒ Others.....
- iii. Delineation of impacted area
☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW
7. Type of properties/ structures, if any, found outside the right-of-way
☒ Crops ☒ Fish Farm/ Pond ☒ Fishing net ☐ Makeshift
☒ Permanent ☒ Others

8. Extent of Impact

a) Community (indicate name)

b) Land (indicate area in m²)

i.

ii.

iii.

iv.

iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Rel.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken.....

11. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

12. Remarks/Recommendation NAOC SHOULD CARRY OUT

REGULAR CHECKS ON ITS FACILITIES

13. Time investigation ended

1608 HRS.