



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: S.P.D.C

2. Type of Complaint/Incident:

- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify) NON LEAKING

3. Incident Details

- i. Date of Incident: 20/10/2015 ii. Date first reported: 21/10/2015
iii. Date of first investigation: 19/11/2015
iv. Date of follow-up investigation: 20/11/2015
v. Time investigation started:
vi. Estimated quantity spilled: NIL

4. Site Details

- i. Site/Location: 12" IMO RIVER - OGAE T/L AT KAMKOM
ii. Position of Spill/Leak: NHT N OIL 8566U
E 007 16463
iii. Spill area
☐ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☐ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☐ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland
- ☐ Fish Pond
- ☐ Vegetation
- ☐ Fishing Net
- ☐ Surface water
- ☐ Venerable Objects
- ☐ Others (Specify)

ii. Nature of impact

- ☐ Oil stained vegetation
- ☐ Oil stained fishing nets
- ☐ Dead floating fishes
- ☐ Dead floating crabs
- ☐ Withering of vegetation
- ☐ Others (Specify)

iii. Delineation of Impacted area

- ☐ Within Company’s facility/ROW
- ☐ Outside Company’s facility/ROW

7. Extent of Impact

- (a) Community (Indicate name)
- (b) Land (Indicate area in m²)

- i.i.
- ii.ii.
- iii.iii.
- iv.iv.

- (c) Creek/Creek lets
- ☐ Tidal
- ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

- (d) Swamp
- ☐ Tidal
- ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

- (e) River
- ☐ Tidal
- ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

- (f) Shoreline/water
- ☐ Tidal
- ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☐ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation..... *suspected non-leak crude theft,*
which was investigated and concluded not to
be theft.

12. Time Investigation ended.....

13. Name and Signature of Participants