

SOME PHOTOGRAPHS TAKEN DURING THE JIV



Fig A: The Incident Facility




Fig B: The leak point (Hacksaw cut)



Fig C: Leak point pegged during repair



Fig D: The Leak Point after repair