

SOME PHOTOGRAPHS TAKEN DURING THE JIV



Fig A: The Incident Facility before excavation



Fig B: The Incident Facility just after excavation.



Fig C: The Incident Facility after repair



Fig D: Backfill