

SOME PHOTOGRAPHS TAKEN DURING THE JIV



Fig A: Incident Area just before excavation



Fig B: The leak point (Hacksaw cut)



Fig C: Leak point pegged during repair.



Fig D: Incident Facility after repair.