

## SOME PHOTOGRAPHS TAKEN DURING THE JIV



Fig A: Incident Area just before excavation



Fig B: The leak point (Hacksaw cut)



Fig C: Strands of crude oil in the adjoining swamp



Fig D: Incident Facility during repair.