

SOME PHOTOGRAPHS TAKEN DURING THE JIV



Fig A: NAOC's RoW & adjoining swamp completely covered with crude oil



Fig B: A Creek off the RoW full of crude oil




Fig C: Few out of several dead crabs in the adjoining swamp.



Fig D: Another section of the RoW filled with crude



Fig E: The spill point after excavation



Fig F: Incident Facility during repair



Fig G: Incident Facility after repair