

PHOTOGRAPHS TAKEN DURING JIV



Fig A: picture taken after excavation.



Fig B: picture after exposing wrap.



Fig C: picture taken after repair.



Fig D: picture taken after backfilled.