



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY
2. Type of Complaint/Incident:
☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify).....
3. Incident Details
 - i. Date of Incident: 05/06/2017 ii. Date first reported: 05/06/2017
 - iii. Date of first investigation: 05/06/17 iv. Spill Incident No: 2017/SAR/NL/024
 - v. Date of follow-up investigation:
 - vi. Time investigation started: 11:40 HRS
 - vii. Estimated quantity spilled(bbls): NIL viii. Quantity Recovered: NIL
4. Site Details
 - i. Site/Location: 18" TERIBABA/BRASS PIPE LINE AT MBIKIRA
 - ii. State: BAYELSA iii. L.G.A: SOUTHERN IJAW
 - iv. Spill Co-Ordinates: N(m) 04° 29' 02.2"
E(m) 006° 05' 51.6"
 - v. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (specify).....
 - iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify) N/A
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☒ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
 - ii. Type of Oil contaminant
☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify) N/A
 - iii. Facility
☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....
 - iv. Cause of Spill
☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (specify).....
 - v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (specify).....



6. Impact of Incident

i Properties impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
☐ Others (specify)..... *N/A*

ii. Nature of impact

- ☒ Oil stained vegetation
☒ Oil stained fishing nets
☒ Dead floating fishes
☒ Dead floating crabs
☒ Withering of vegetation
☒ Others... *N/A*

iii. Delineation of impacted area

- ☐ Within Company's facility/ROW
☐ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops
☒ Fish Farm/ Pond
☒ Fishing Net
☒ Makeshift
☒ Permanent
☒ Others ... *N/A*

8. Extent of Impact

a) Community (indicate name)

- i.
 ii.
 iii.
 iv.

b) Land (indicate area in m^2)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
.....			
.....			
.....			

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
.....			
.....			
.....			

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
.....			
.....			
.....			

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
.....			
.....			
.....			

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken..... N/A

11. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation..... ALL AREA'S VISITED FOR JLV
SHOULD BE PROPERLY MONITORED.

13. Time investigation ended..... 12:27 HRS