



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: SPDC - 1846228, 1846217, 1846233, 1846247
2. Type of Complaint/Incident:
☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify) NON-LEAKING POINT
3. Incident Details
 - i. Date of Incident: 11-7-2017 ii. Date first reported:
 - iii. Date of first investigation: 12-07-2017
 - iv. Date of follow-up investigation: 12-07-2017
 - v. Time investigation started:
 - vi. Estimated quantity spilled: NIL
4. Site Details
 - i. Site/Location: 12' IMO RIVER-OGALE TRUNKLINE @ KOMKOM
 - ii. Position of Spill/Leak: 12' O' CLOCK
 - iii. Spill area
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify)
 - iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify)
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
 - ii. Type of Oil contaminant
☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify) NON-LEAKING
 - iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify)
 - iv. Cause Of Spill
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify) OIL THEFT
 - v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify) INSTALLED VALVE

8. Documentary Evidence

☐ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken ☐ Yes ☐ No

10. Sample Type(s) ☐ Soil ☐ Water ☐ Sediment ☐ Others (Specify).....

11. Investigation carried out by

☐ Foot ☐ Boat ☐ Aircraft

12. Remarks/General comments.....

INCREASE SECURITY PRESENCE ON
THE PIPELINE ROW

13. Recommendations: REPAIR AFFECTED PIPELINE