

PICTURES ON SITE:



Figure 1: BEFORE EXCAVATION



Figure 2: AFTER EXCAVATION 3" NIPPLE 3" BALL VALVE FOUND



FIGURE: 3 REPAIR WORK