



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: SPDC.
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
i. Date of Incident: 21/07/17 ii. Date first reported: 1/08/2017
iii. Date of first investigation: 4/08/2017
iv. Date of follow-up investigation: —
v. Time investigation started: 13:28 hours
vi. Estimated quantity spilled: 42.64 bbls
4. Site Details
i. Site/Location: Imo River 1 Well S S Flowline
ii. Position of Spill/Leak: 4.98404 7.17859
iii. Spill area
☒ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☐ 12 O' Clock ☒ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)
- iii. Facility
☐ Pipeline ☒ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....
- iv. Cause Of Spill
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....
- v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify).....

6. Impact of Incident

i Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

- i. Igri-Ukwu
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i. 0.1245 Ha.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs

☐ Video coverage

☒ Mapping

9. Samples taken.....

NO

10. Investigation carried out by

☒ Foot

☐ Boat

☐ Aircraft

11. Remarks/Recommendation.....

The company should
start immediate clean up of the
impacted areas.

12. Time investigation ended.....

16:40 hours.