



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: S.P.D.R.

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 27th JUNE 2017 ii. Date first reported: 27th JUNE 2017
iii. Date of first investigation: 30th JUNE 2017
iv. Date of follow-up investigation:
v. Time investigation started: 1.5:20 PM
vi. Estimated quantity spilled: 134.49 bbls

4. Site Details

- i. Site/Location: 12 IMD RIVER - OGARE PIPELINE
ii. Position of Spill/Leak: N 4° 56' 3.6.2034" E 7° 11' 5.2434"

iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 0'Clock ☐ 10 0'Clock ☐ 2 0'Clock ☐ 3 0'Clock
☐ 4 0'Clock ☐ 5 0'Clock ☐ 6 0'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☒ Others (Specify) ... PALM TREES

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify)

iii. Delineation of Impacted area

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i.
 ii.
 iii.
 iv.

(b) Land (Indicate area in m²)

- i.
 ii.
 iii.
 iv.

(c) Creek/Creek lets

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☐ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation. OIL SPILL RECOVERY AND REPAIR ACTIVITIES
ARE ONGOING. / SURVEILLANCE ON FACILITY SHOULD BE
IMPROVED.

12. Time Investigation ended.....