



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

*Note: This JIV Form is to be completed and signed by all participating parties in the field*

1. Company: NIGERIAN AGIP OIL COMPANY (NAOC)
2. Type of Complaint/Incident:  
☒ Oil Pollution    ☐ Fire/Explosion    ☐ Drilling Mud/Chemical Pollution  
☐ Others (Specify).....
3. Incident Details
  - i. Date of Incident: 06/05/2017    ii. Date first reported: 06/05/2017
  - iii. Date of first investigation: 06/05/2017    iv. Spill Incident No: 2017/SAR/NL/018
  - v. Date of follow-up investigation: 07/05/2017
  - vi. Time investigation started: 08:20AM
  - vii. Estimated quantity spilled(bbls): N/A    viii. Quantity Recovered: N/A
4. Site Details
  - i. Site/Location: 18" TEBIDABA / BRASS PIPELINE @ OBEREGBENE
  - ii. State: BAJELSA    iii. L.G.A: SOUTHERN IAN LOCAL GOVT.
  - iv. Spill Co-Ordinates: N(m) 04° 30' 18.3"  
E(m) 006° 03' 22.6"
  - v. Spill area  
☐ Land    ☒ Swamp    ☐ Freshwater    ☐ Mangrove    ☐ Coastline  
☐ Near shore    ☐ Offshore    ☐ Others (specify).....
  - iv. Structural Controls in Place  
☐ Boom    ☐ Trenches    ☐ Bund wall    ☐ Sorbents    ☐ Others (specify) N/A
5. Circumstances Around Spill Point
  - i. Visual observation of Hole Position  
☒ 12 O' Clock    ☐ 10 O' Clock    ☐ 2 O' Clock    ☐ 3 O' Clock  
☐ 4 O' Clock    ☐ 5 O' Clock    ☐ 6 O' Clock
  - ii. Type of Oil contaminant  
☒ Crude Oil    ☐ Condensate    ☐ Chemicals    ☐ Refined Products  
☐ Others (specify) .....
  - iii. Facility  
☒ Pipeline    ☐ Flow line    ☐ Wellhead    ☐ Manifold    ☐ Flow Station    ☐ Rig  
☐ Storage Tank    ☐ Compressor Plant    ☐ Others (specify).....
  - iv. Cause of Spill  
☐ Corrosion    ☐ Equipment Failure    ☒ Third Party Interference    ☐ Accident  
☐ Operational Error    ☐ Others (specify).....
  - v. Visible Sign of Third Party Interference  
☐ Hacksaw Marks    ☐ Drilled Holes    ☐ Blasting    ☐ Theft    ☐ Acid  
☐ Others (specify) CONE OF A PREVIOUSLY REPAIR BUNKERING POINT WAS CUT OF BY UNKNOWN PERSON FOR OIL THEFT ACTIVITIES



6. Impact of Incident

i Properties impacted by the incident

- ☐Farmland    ☐Fish Pond    ☐Vegetation    ☐Fishing Net    ☐Surface water  
☐Venerable Objects    ☐Others (specify)..... *N/A*

ii. Nature of impact

- ☐Oil stained vegetation    ☐Oil stained fishing nets    ☐Dead floating fishes  
☐Dead floating crabs    ☐Withering of vegetation    ☐Others..... *N/A*

iii. Delineation of impacted area

- ☒Within Company’s facility/ROW    ☐Outside Company’s facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops    ☐ Fish Farm/ Pond    ☐ Fishing Net    ☐ Makeshift  
☐ Permanent    ☐ Others ..... *N/A*

8. Extent of Impact

a) Community (indicate name)

- i. ....  
ii. ....  
iii. ....  
iv. ....

b) Land (indicate area in m<sup>2</sup>)

- i. ....  
ii. ....  
iii. ....  
iv. ....

b) Creeks/Creek lets

- ☐Tidal    ☐Non-tidal

| NAME  | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|-------|--------------------|-----------------|----------------|
| ..... | .....              | .....           | .....          |
| ..... | .....              | .....           | .....          |
| ..... | .....              | .....           | .....          |

c) Swamp

- ☐Tidal    ☐Non-tidal

| NAME  | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|-------|--------------------|-----------------|----------------|
| ..... | .....              | .....           | .....          |
| ..... | .....              | .....           | .....          |
| ..... | .....              | .....           | .....          |

d) River

- ☐Tidal    ☐Non-tidal

| NAME  | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|-------|--------------------|-----------------|----------------|
| ..... | .....              | .....           | .....          |
| ..... | .....              | .....           | .....          |
| ..... | .....              | .....           | .....          |

e) Shoreline/water

| NAME  | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|-------|--------------------|-----------------|----------------|
| ..... | .....              | .....           | .....          |
| ..... | .....              | .....           | .....          |
| ..... | .....              | .....           | .....          |

9. Photograph/Map/Chart Ref.

☒ Still photographs    ☐ Video coverage    ☐ Mapping

10. Samples taken..... N/A

11. Investigation carried out by

☐ Foot    ☒ Boat    ☐ Aircraft

12. Remarks/Recommendation..... N/AOC SHOULD INTENSIFY  
SECURITY ALONG ITS FACILITIES.

13. Time investigation ended..... 09:46 AM