

PICTURES TAKEN AT SITE:



SPILL POINT BEFORE EXCAVATION (POINT A)



SPILL POINT BEFORE EXCAVATION (POINT B)




SPILL POINT AFTER EXCAVATION (POINT A)



SPILL POINT AFTER EXCAVATION (POINT B)



WORK DONE BY NAOC REPAIR TEAM (POINT A)



WORK DONE BY NAOC REPAIR TEAM (POINT B)