




**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

*Note: This JIV Form is to be completed and signed by all participating parties in the field*

1. Company: NIGERIAN AGIP OIL COMPANY (NAOC)
2. Type of Complaint/Incident:  
☒ Oil Pollution    ☐ Fire/Explosion    ☐ Drilling Mud/Chemical Pollution  
☐ Others (Specify).....
3. Incident Details
  - i. Date of Incident: 05/07/2017 ii. Date first reported: 05/07/2017
  - iii. Date of first investigation: 07/07/2017 iv. Spill Incident No: 2017/LAR/077/122
  - v. Date of follow-up investigation: .....
  - vi. Time investigation started: 4:00pm
  - vii. Estimated quantity spilled(bbls): 10 bbls viii. Quantity Recovered: NIL
4. Site Details
  - i. Site/Location: TAYLOR CREEK 2L & S WELL HEAD IKARAMA
  - ii. State: BAYELSA iii. L.G.A: YENAGOA
  - iv. Spill Co-Ordinates: N(m) 05° 10' 36.39"  
E(m) 006° 26' 36.17"
  - v. Spill area  
☒ Land    ☐ Swamp    ☐ Freshwater    ☐ Mangrove    ☐ Coastline  
☐ Near shore    ☐ Offshore    ☐ Others (specify).....
  - iv. Structural Controls in Place  
☒ Boom    ☐ Trenches    ☐ Bund wall    ☐ Sorbents    ☐ Others (specify).....
5. Circumstances Around Spill Point
  - i. Visual observation of Hole Position  
☐ 12 O' Clock    ☐ 10 O' Clock    ☐ 2 O' Clock    ☐ 3 O' Clock  
☐ 4 O' Clock    ☐ 5 O' Clock    ☐ 6 O' Clock
  - ii. Type of Oil contaminant  
☒ Crude Oil    ☐ Condensate    ☐ Chemicals    ☐ Refined Products  
☐ Others (specify) .....
  - iii. Facility  
☐ Pipeline    ☐ Flow line    ☒ Wellhead    ☐ Manifold    ☐ Flow Station    ☐ Rig  
☐ Storage Tank    ☐ Compressor Plant    ☐ Others (specify).....
  - iv. Cause of Spill  
☐ Corrosion    ☐ Equipment Failure    ☒ Third Party Interference    ☐ Accident  
☐ Operational Error    ☐ Others (specify) STOLEN SSV & CHORE BOX
  - v. Visible Sign of Third Party Interference  
☐ Hacksaw Marks    ☐ Drilled Holes    ☐ Blasting    ☒ Theft    ☐ Acid  
☐ Others (specify).....



6. Impact of Incident

i. Properties impacted by the incident

- ☐ Farmland    ☐ Fish Pond    ☐ Vegetation    ☐ Fishing Net    ☐ Surface water  
☐ Venerable Objects    ☐ Others (specify)..... *nil*

ii. Nature of impact

- ☐ Oil stained vegetation    ☐ Oil stained fishing nets    ☐ Dead floating fishes  
☐ Dead floating crabs    ☐ Withering of vegetation    ☐ Others..... *nil*

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW    ☐ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops    ☐ Fish Farm/ Pond    ☐ Fishing Net    ☐ Makeshift  
☐ Permanent    ☐ Others ..... *nil*

8. Extent of Impact

a) Community (indicate name)

- i. ....  
ii. ....  
iii. ....  
iv. ....

b) Land (indicate area in m<sup>2</sup>)

- i. ....  
ii. ....  
iii. ....  
iv. ....

b) Creeks/Creek lets

- ☐ Tidal    ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

c) Swamp

- ☐ Tidal    ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

d) River

- ☐ Tidal    ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

e) Shoreline/water

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

9. Photograph/Map/Chart Ref.

☒ Still photographs    ☐ Video coverage    ☐ Mapping

10. Samples taken.....

11. Investigation carried out by

☒ Foot    ☐ Boat    ☐ Aircraft

12. Remarks/Recommendation. *NAOC should carry out an immediate clean up on the site, to avoid further spread of crude oil.*

13. Time investigation ended. *5:00pm*