

6. Impact of Incident

i Properties impacted by the incident

- ☐Farmland ☐Fish Pond ☐Vegetation ☐Fishing Net ☐Surface water
☐Venerable Objects ☐Others (specify)..... N/A

ii. Nature of impact

- ☐Oil stained vegetation ☐Oil stained fishing nets ☐Dead floating fishes
☐Dead floating crabs ☐Withering of vegetation ☐Others... IMPACT ALONG ROW

iii. Delineation of impacted area

- ☐Within Company's facility/ROW ☐Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

- i. AZARBE NE
ii.
iii.
iv.

b) Land (indicate area in m²)

- i.
ii.
iii.
iv.

b) Creeks/Creek lets

- ☐Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

- ☐Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

- ☐Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....

- NIL -

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation.....

AREA REQUIRES CLEANUP

NAOC SHOULD IMPROVE ON SURVEILLANCE OF
LTS ASSETS

12. Time investigation ended.....