



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: SHELL PETROLEUM DEVELOPMENT COMPANY (SPDC)

2. Type of Complaint/Incident:

- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)..... ASSET DAMAGE

3. Incident Details

i. Date of Incident: 02 / 04 / 2017 ii. Date first reported: 03 / 04 / 2017

iii. Date of first investigation: 08 / 04 / 2017 iv. Spill Incident No.: 1832918

v. Date of follow-up investigation:

vi. Time investigation started: 12:28 HRS

vii. Estimated quantity spilled(bbls): NIL viii. Quantity Recovered: NIL

4. Site Details

i. Site/Location: OPUKUSHI WELL 24T WELLHEAD @ EGBEMO ANGALABIRI \$AGBIDIAMA

ii. State: BAYELSA iii. L.G.A: EKEREMOR

iv. Spill Co-Ordinates: N(m) 04° 55' 17.0"
E(m) 005° 44' 37.5"

v. Spill area

- ☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....

Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock

ii. Type of Oil contaminant

- ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)

iii. Facility

- ☐ Pipeline ☐ Flow line ☒ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify) TAMPERED SURVEY CAP

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify) THE SURVEY CAP ON THE WELL 24T WELLHEAD WAS TAMPERED WITH BY UNKNOWN PERSON.



6. Impact of Incident

i Properties impacted by the incident

- ☐Farmland ☐Fish Pond ☐Vegetation ☐Fishing Net ☐Surface water
☐Venerable Objects ☐Others (specify)..... NIL

ii. Nature of impact

- ☐Oil stained vegetation ☐Oil stained fishing nets ☐Dead floating fishes
☐Dead floating crabs ☐Withering of vegetation ☐Others.... NIL

iii. Delineation of impacted area

- ☐Within Company's facility/ROW ☐Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing Net ☐ Makeshift
☐ Permanent ☐ Others NIL

8. Extent of Impact

a) Community (indicate name)

- i.
ii.
iii.
iv.

b) Land (indicate area in m²)

- i.
ii.
iii.
iv.

b) Creeks/Creek lets

☐Tidal

☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐Tidal

☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐Tidal

☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken..... N/A

11. Investigation carried out by

☐ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation SPDC SHOULD INTENSIFY SECURITY
ALONG ITS FACILITY.
SPDC SHOULD FOLLOW PROCEDURE.

13. Time investigation ended..... 15:30 HRS