



Naoc

POST CLEAN UP JOINT INSPECTION REPORT

1.	SPILL REF. NO.:	2017/LAR/041/069		
2.	SPILL LOCATION:	OBHAFU 29 LS PSS FLANGE (a) Well Loc. Onsky		
3.	CO-ORDINATES:			
4.	DATE OF INSPECTION:	30-11-2017		
5.	SPILL DETAILS	DATE OF SPILL	CAUSE OF SPILL	QTY SPILLED
		23-03-2017	SABOTAGE	0.066BL
6.	DATE CLEAN UP COMMENCED:	07-04-2017		
7.	CONTRACTOR:	IN - HOUSE		
8.	CONTRACT NO.:			
9.	CLEAN UP METHOD:	MECHANICAL ☒	MANUAL ☒	OTHERS ☒
	IF OTHERS, SPECIFY			
10.	CLEAN UP DURATION	DATE CLEAN UP COMPLETED	TOTAL DURATION OF CLEAN UP	
		07-04-2017	ONE DAY	
11.	ANY INCIDENT DURING CLEAN UP?	YES ☐	NO ☒	
	IF YES, WHAT TYPE			
12.	ANY CASUALTY/INJURY?	YES ☐	NO ☒	
	IF YES, HOW WAS IT MANAGED?			
13.	VISUAL OBSERVATIONS: (TICK AS APPROPRIATE)			
	ANY OIL SHEEN ON WATER?	YES ☐	NO ☒	NA ☐
	ANY OIL STAIN ON VEGETATION?	YES ☐	NO ☒	NA ☐
	IS SOIL WET WITH OIL?	YES ☐	NO ☒	NA ☐
	ANY PATCHES OF OIL ON IMPACTED AREA?	YES ☐	NO ☒	NA ☐
	IS DISPOSAL OF OIL DEBRIS SATISFACTORY?	YES ☒	NO ☐	NA ☐
	WAS DISPERSANT APPLIED?	YES ☐	NO ☒	NA ☐

14. COMMUNITY ASSESSMENT:	VERY GOOD ☐	GOOD ☐	SATISFACTORY ☒	POOR ☐
---------------------------	------------------------------------	-------------------------------	--	-------------------------------

15. ANY SAMPLES COLLECTED?	YES ☐	NO ☒
----------------------------	------------------------------	--

16. IF YES, WHAT TYPE	SOIL ☒	WATER ☒
-----------------------	--	---

17. RECOMMENDATION:	Site was properly cleaned and PCI team confirmed it satisfactory. However samples were not collected due the site was concretized and no water in the cellar pit.
---------------------	---

18. CONCLUSION (INDICATE WHETHER CLEAN UP IS CERTIFIED AS):	SATISFACTORILY ☒	NOT SATISFACTORY ☐	POOR ☐
---	--	---	-------------------------------

INSPECTION TEAM:

NAOC	littlelike Oluwa	Site monitor		30/11/17
	NAME	DESIGNATION	SIGNATURE	DATE

DPR				
	NAME	DESIGNATION	SIGNATURE	DATE

NOSDRA	Godspower Isheke	SES		30/11/17
	NAME	DESIGNATION	SIGNATURE	DATE

SMENV	Mankie-Tanen B	SCE		30/11/17
	NAME	DESIGNATION	SIGNATURE	DATE

CONTRACTOR	IN-HOUSE			
	NAME	DESIGNATION	SIGNATURE	DATE

COMMUNITY				
	NAME	DESIGNATION	SIGNATURE	DATE

OTHERS				
	NAME	DESIGNATION	SIGNATURE	DATE

SPILL SITE ASSESSMENT / SAMPLING JOINT REPORT

1. SPILL DETAILS

- (a) Spill Reference No.: 2017/LAR/041/069
(b) Spill Location: OBIATU 29LS PSS FLANGE @ WELL LOC Omukey
(c) Date of spill: 23-03-2017
(d) Cause of spill: SABOTAGE

2. SITE DETAILS:

2.1 Media impacted: (a) Soil ☐(c) Water body ☐ (d) Others

2.2 Area of impact:

2.3 Distance of site from farmland, settlement and/or natural

ecosystem(s) (a) < 100m ☐ (b) < 1km ☐

3. Visual inspection / observation:

Visually the site was properly cleaned
and confirmed satisfactory by p.ei team.
However samples were not collected due the
wellhead ~~was~~ is concretized and no water
in the cellar pot.

4. Sample collection:

Sl. No.	Date of sample collection	Type of samples					
		Soil					Remarks
		Top 10 cm	Below 10 cm	Below 20 cm	Below 30 cm	Below 40 cm	
1							
2							
3							

Summary:

Total no. of soil samples collected:

Total no. of water samples collected:

Total no. of control soil samples collected:

Overall no of samples collected:

5. Remarks/Recommendation:

Site Confirmed Satisfactory by PCI team.

Name: Ulesike Owele Sign: [Signature] Representing: NAOE

Name: Godspower Isheke Sign: [Signature] Representing: NOSDRA 30/11/17

Name: Mankie - Tanen B Sign: [Signature] Representing: RS/HEMV 30/11/17

Name: Sign: Representing:


Name: Sign: Representing:

Name: Sign: Representing:

Dated this 30/11/17 day of Nov 2017

OIL SPILL SITE JOINT INVESTIGATION VISIT ATTENDANCE SHEET

LOCATION/SPILL SITE: Obiafu 29 LS, 855 Flange (9) Well Loc. Omu KySPILL REF. NO: 2017/LAT/1041/089DATE OF SPILL: 23-03-2017DATE OF INSPECTION: 30 Jul 17

S/no.	Name	Company / Organization / Community	Signature / Date
1	Ucheoke Okwe	NADRA ENV	 30 Jul 17
2	Godspower Ishoke	NOSDRA	 30 Jul 17
3	Mankie-Tanen B	RSMEAN	 30/11/17.

Name of Responsible: Ucheoke Okwe Signature:  30 Jul 17