



2018/SAR/004

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: AFRICAN AGIP OIL COMPANY (NADO)

2. Type of Complaint/Incident:

☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution

☐ Others (Specify).....

3. Incident Details

i. Date of Incident: 14/01/2018 ii. Date first reported: 14/01/2018

iii. Date of first investigation: 15/01/2018

iv. Date of follow-up investigation:

v. Time investigation started: 8:00 HRS

vi. Estimated quantity spilled: 0.0628

4. Site Details

i. Site/Location: OCCOINBIRI DEEP 3T WELL

ii. Position of Spill/Leak: FLANGE LEAKAGE

iii. Spill area

☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline

☐ Near shore ☐ Offshore ☐ Others (specify).....

iv. Structural Controls in Place

☒ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock

☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock

FLANGE

ii. Type of Oil contaminant

☐ Crude Oil ☒ Condensate ☐ Chemicals ☐ Refined Products

☐ Others (specify)

iii. Facility

☐ Pipeline ☐ Flow line ☒ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig

☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....

iv. Cause Of Spill

☐ Corrosion ☒ Equipment Failure ☐ Third Party Interference ☐ Accident

☐ Operational Error ☐ Others (specify).....

v. Visible Sign of Third Party Interference

☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid

☐ Others (specify)..... N/A

LEAKAGE DUE TO FLANGE FAILURE

6. Impact of Incident

i Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

- i. Laborn Bika
 ii.
 iii.
 iv.

b) Land (indicate area in m^2)

- i. 3.33 m^2
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. **Photograph/Map/Chart Ref.**

☒ Still photographs ☐ Video coverage ☐ Mapping

9. **Samples taken**.....

10. **Investigation carried out by**

☐ Foot ☒ Boat ☐ Aircraft

11. **Remarks/Recommendation**..... AREA REQUIRES NO FURTHER
INTERVENTION. RECOMMENDED FOR NATURAL
ATTENUATION.....

12. **Time investigation ended**..... 16:30 HRS.....