

PHOTOGRAPHS TAKEN ON SITE



FIG 1 Spill point on arrival at site



FIG 2: Spill point



FIG 3: Heavy impact along the Gbaraun Creek




Fig 4: Impact drifting towards the Gbaraun River