



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY (NAOC)
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
 - i. Date of Incident: 20 / 03 / 18 ii. Date first reported: 20 / 03 / 2018
 - iii. Date of first investigation: 21 / 03 / 18 iv. Spill Incident No: 2018/SAR/014
 - v. Date of follow-up investigation:/...../.....
 - vi. Time investigation started: 12:20 HRS
 - vii. Estimated quantity spilled(bbls): 1.04 BBL viii. Quantity Recovered: 0.691 BBL
4. Site Details
 - i. Site/Location: 10" CLOUGH-CREEK / TERIDABA P/L @ GBARAUN
 - ii. State: BAYELSA iii. L.G.A: SOUTHERN IJAW
 - iv. Spill Co-Ordinates: N(m) 04° 46' 41.5"
E(m) 005° 46' 53.7"
 - v. Spill area
☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
 - iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
☐ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
 - ii. Type of Oil contaminant
☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)
 - iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....
 - iv. Cause of Spill
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....
 - v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (specify).....



6. Impact of Incident

i Properties impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
 ☒ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
☒ Dead floating crabs
 ☒ Withering of vegetation
 ☒ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW
 ☐ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops
 ☐ Fish Farm/ Pond
 ☐ Fishing Net
 ☐ Makeshift
☐ Permanent
☐ Others

8. Extent of Impact

a) Community (indicate name)

- i.
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i. 189,903 m²
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☐ Mapping

10. Samples taken.....

11. Investigation carried out by

☒ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation (U) IMMEDIATE REPAIR OF AFFECTED FACILITY

(U) SURVEILLANCE/SECURITY AROUND THE ASSET(S) SHOULD BE IMPROVED

13. Time investigation ended 13:45 HRS