



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY (NAOC)
2. Type of Complaint/Incident:
☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify) GASEOUS EMISSION
3. Incident Details
i. Date of Incident: 16 / 08 / 2017 ii. Date first reported: 16 / 08 / 2017
iii. Date of first investigation: 23 / 08 / 2017 iv. Spill Incident No: 2017/LAR/GL1/024
v. Date of follow-up investigation: _____
vi. Time investigation started: 01:23 PM
vii. Estimated quantity spilled(bbls): N/A viii. Quantity Recovered: N/A

4. Site Details
i. Site/Location: 6" TUOMO - OGBOINBIRI PIPELINE AT OGBOINUWARI
ii. State: BAVELZA iii. L.G.A: EKEREMOR
iv. Spill Co-Ordinates: N(m) N 04° 57' 51.1"
E(m) E 005° 55' 58.5"
v. Spill area
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify) SEASONAL SWAMP
iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify) N/A

5. Circumstances Around Spill Point

- i. Visual observation of Hole Position
☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock ; 8-11 O'clock
- ii. Type of Oil contaminant
☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify) GASEOUS EMISSION
- iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify) _____
- iv. Cause of Spill
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify) _____
- v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify) HACKSAW CUT OF ABOUT 110MM WAS OBSERVED ON THE FACILITY AT 8-11 O'CLOCK POSITION BY VANDAL.



6. Impact of Incident

i Properties impacted by the incident

- ☐Farmland ☐Fish Pond ☐Vegetation ☐Fishing Net ☐Surface water
☐Venerable Objects ☐Others (specify)..... N/A

ii. Nature of impact

- ☐Oil stained vegetation ☐Oil stained fishing nets ☐Dead floating fishes
☐Dead floating crabs ☐Withering of vegetation ☐Others... N/A

iii. Delineation of impacted area

- ☐Within Company's facility/ROW ☐Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing Net ☐ Makeshift
☐ Permanent ☐ Others... N/A

8. Extent of Impact

a) Community (indicate name)

- i.
ii.
iii.
iv.

b) Land (indicate area in m²)

- i.
ii.
iii.
iv.

b) Creeks/Creek lets

- ☐Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

- ☐Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

- ☐Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken

11. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

12. Remarks/Recommendation

INTENSIFY SECURITY AND IMPROVE
SURVEILLANCE ON THE FACILITY.

13. Time investigation ended

02:23 PM