

SOME PHOTOGRAPHS TAKEN DURING THE JOINT INVESTIGATION VISIT



Fig A: Incident Area on arrival of the JIT



Fig B: Incident Facility after excavation



Fig C: Impacted Area



Fig D: Incident facility shortly after repair