



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
 - i. Date of Incident: 18 / 04 / 18 ii. Date first reported: 18 / 04 / 18
 - iii. Date of first investigation: 19 / 04 / 18 iv. Spill Incident No.: 2018/LAR/053
 - v. Date of follow-up investigation: 20 / 04 / 2018
 - vi. Time investigation started: 14:10 HRS
 - vii. Estimated quantity spilled(bbls): 4.1 viii. Quantity Recovered: NIL
4. Site Details
TAYLOR CREEK 2S FLOWLINE AT KALABA,
AKUMONI AND AYAMABELE
 - i. Site/Location:
 - ii. State: BAYELSA iii. L.G.A: YENAGOA
 - iv. Spill Co-Ordinates: N(m) 05° 07' 45.5"
E(m) 006° 27' 20.6"
 - v. Spill area
☒ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
 - iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
 - ii. Type of Oil contaminant
☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)
 - iii. Facility
☐ Pipeline ☒ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....
 - iv. Cause of Spill
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....
 - v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify).....



6. Impact of Incident

i Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing Net ☐ Makeshift
☐ Permanent ☐ Others

8. Extent of Impact

a) Community (indicate name)

- i.
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i. 28 m²
 ii.
 iii.
 iv.

b) Creeks/Creek lets

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken.....

11. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

12. Remarks/Recommendation (C) CLEAN-UP OF IMPACTED AREA
(u) SURVEILLANCE/SECURITY SHOULD BE ENHANCED

13. Time investigation ended 15:30 HRS