

SOME PHOTOGRAPHS TAKEN DURING THE JOINT INVESTIGATION VISIT



Fig A: Incident Area on arrival of the JIT





Fig B & C: The Leak Points



Fig D: Impacted Area



Fig E: Incident facility shortly after repair