

JOINT INVESTIGATION VISIT (JIV) FORM

JOINT INVESTIGATION VISIT (JIV) FORM
Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: ALAC

2. Type of Complaint/Incident:

- Type of Complaint/Incident:
- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
- ☒ Others (Specify) GAS 2005 GMS 510M

3. Incident Details

- Others (Specify) 29/01/2017
- Incident Details**
- i. Date of Incident: 29/01/2017
- ii. Date first reported: 29/01/2017
- iii. Date of first investigation: 31/01/2017
- iv. Date of follow-up investigation: N/A
- v. Time investigation started: 1457 HRS
- vi. Estimated quantity spilled: N/A

4. Site Details

- Details**
- i. Site/Location: GR1AFU 2P FLOWLINE PLANKS BY THE GATE VALVE
- ii. Position of Spill/Leak: NOS 2F 52.1" E DOG 35' 43.8"
- iii. **Spill area**
- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
- ☐ Near shore ☐ Offshore ☐ Others (Specify).....
- iv. **Structural Controls in Place**
- ☐ Boom ☐ Trenches ☒ Bund Wall ☐ Sorbents ☐ Others (Specify).....

5. Circumstances Around Spill Point

- i. Visual observation of Hole Position**
- ☐ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock
- ii. Type of Oil Contaminant**
- ☐ Crude Oil ☒ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)
- iii. Facility**
- ☐ Pipeline ☒ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)
- iv. Cause of Spill**
- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)
- v. Visible Sign of Third Party Interference**
- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (Specify)

ii. Nature of impact

☐ Oil stained vegetation

☐ Dead floating crabs

☐ Oil stained fishing nets

☐ Withering of vegetation

☐ Dead floating fishes

☐ Others (Specify)

iii. Delineation of Impacted area

☒ Within Company's facility/ROW

☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

i. OLLAS

ii.

iii.

iv.

(b) Land (Indicate area in m²)

i.

ii.

iii.

iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>

19. Graph/Map/chart Ref.

☒ Still photographs



Video coverage



Mapping

9. Samples taken..... 1/1

10. Investigation carried out by



Foot



Boat



Aircraft

11. Remarks/Recommendation..... I.V. was completed and Viper was done on site.

⇒ Improve Surveillance on the well location.....

12. Time Investigation ended..... 17:00 HRS

13. Name and Signature of Participants



NOSDRA

1. ADENIYI OLUSOLA A

21/01/2017 11:11