



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

*Note: This JIV form is to be completed and signed by all participating parties in the field*

1. Company: EROTON EXPLORATION AND PRODUCTION LIMITED

2. Type of Complaint/Incident:

- ☒ Oil Pollution      ☐ Fire/Explosion      ☐ Drilling Mud/Chemical Pollution  
☐ Others (Specify) .....

3. Incident Details

- i. Date of Incident: 27-02-2019      ii. Date first reported: .....  
iii. Date of first investigation: 28-02-2019 .....  
iv. Date of follow-up investigation: .....  
v. Time investigation started: 11:30 HRS .....  
vi. Estimated quantity spilled: 02:05 HRS .....

4. Site Details

- i. Site/Location: CANNIBORNE CHANNEL III WELL 415.4" FLOWLINE  
ii. Position of Spill/Leak: 60713-00, 561854-35

iii. Spill area

- ☐ Land      ☒ Swamp      ☐ Freshwater      ☐ Mangrove      ☐ Coastline  
☐ Near shore      ☐ Offshore      ☐ Others (Specify) .....

iv. Structural Controls in Place

- ☐ Boom      ☐ Trenches      ☒ Bund Wall      ☐ Sorbents      ☐ Others (Specify) .....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 O'Clock      ☐ 10 O'Clock      ☐ 2 O'Clock      ☐ 3 O'Clock  
☐ 4 O'Clock      ☒ 5 O'Clock      ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil      ☐ Condensate      ☐ Chemicals      ☐ Refined Products  
☐ Others (Specify) .....

iii. Facility

- ☐ Pipeline      ☒ Flow Line      ☐ Wellhead      ☐ Manifold      ☐ Flow Station      ☐ Rig  
☒ Storage Tank      ☐ Compressor Plant  
☐ Others (Specify) .....

iv. Cause of Spill

- ☒ Corrosion      ☐ Equipment Failure      ☐ Third Party Interference      ☐ Accident  
☐ Operational Error      ☐ Others (Specify) .....

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks      ☐ Drilled Holes      ☐ Blasting      ☐ Theft      ☐ Acid  
☐ Others (Specify) .....

## 6. Impact of Incident

### i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water  
☐ Venerable Objects ☐ Others (Specify) .....

### ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes  
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify) .....

### iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

## 7. Extent of Impact

### (a) Community (Indicate name)

- i. ....  
ii. ....  
iii. ....  
iv. ....

### (b) Land (Indicate area in m<sup>2</sup>)

- i. ....  
ii. ....  
iii. ....  
iv. ....

### (c) Creek/Creek lets

- ☐ Tidal ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (d) Swamp

- ☐ Tidal ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (e) River

- ☐ Tidal ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (f) Shoreline/water

- ☐ Tidal ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

8. Photograph/Map/Chart Ref.

☒ Still photographs    ☐ Video coverage    ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot    ☐ Boat    ☐ Aircraft

11. Remarks/Recommendation.....

Clean-up should be carried  
out immediately to avoid spread

12. Time Investigation ended.....

02:15 HRS