

6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland
- ☒ Fish Pond
- ☒ Vegetation
- ☒ Fishing Net
- ☒ Surface water
- ☒ Venerable Objects
- ☒ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation
- ☒ Oil stained fishing nets
- ☒ Dead floating fishes
- ☒ Dead floating crabs
- ☒ Withering of vegetation
- ☒ Others (Specify) 2/1A

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW
- ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i.
- ii.
- iii.
- iv.

(b) Land (Indicate area in m²)

- i.
- ii.
- iii.
- iv.

(c) Creek/Creek lets ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

MINISTRY OF THE FEDERAL REPUBLIC OF NIGERIA

8. Photograph/Map/Chart Ref.

☒ Still photographs

☐ Video coverage

☐ Mapping

9. Samples taken.....

NIL

10. Investigation carried out by

☒ Foot

☒ Boat

☐ Aircraft

11. Remarks/Recommendation

CLEANUP OF THE IMPACTED AREA SHOULD BE CARRIED OUT IMMEDIATELY. (II) FINGERPRINTING OF THE SUSPECTED CRUDE SHOULD BE CONDUCTED TO DETERMINE ITS SOURCE. (III) SURVEILLANCE SHOULD BE STEPPED UP

12. Time Investigation ended

1.10 p.m.

13. Name and Signature of Participants

❖ NOSDRA



Plate 1: Photographic evidence of impacted area.

