

1. Company:
2. Type of Complaint/Incident:
- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
- ☒ Others (Specify)

Incident Details

- i. Date of Incident: 23RD OCTOBER, 2018 ii. Date first reported: 24TH OCTOBER, 2018
- iii. Date of first investigation: 26TH OCTOBER, 2018
- iv. Date of follow-up investigation:
- v. Time investigation started: 12:45 p.m.
- vi. Estimated quantity spilled: 0.2 Bbls

Site Details

- i. Site/Location: IMO RIVER 1 WELL 37 FLOWLINE, IGIRIUKWU (OWAZA), ABIA
- ii. Position of Spill/Leak: $NO4^{\circ} 59' 32.4''$, $E007^{\circ} 11' 45.1''$
- iii. Spill area
- ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
- ☒ Near shore ☒ Offshore ☒ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

Conditions Around Spill Point

Visual observation of Hole Position

- ☒ 12 O'Clock ☒ 10 O'Clock ☒ 2 O'Clock ☒ 3 O'Clock
- ☒ 4 O'Clock ☒ 5 O'Clock ☒ 6 O'Clock

Type of Oil Contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
- ☒ Others (Specify)

Facility

- ☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
- ☒ Storage Tank ☒ Compressor Plant
- ☒ Others (Specify)

Cause of Spill

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
- ☒ Operational Error ☒ Others (Specify)

Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
- ☒ Others (Specify) ONE INCH VALVE INSTALLED ON FLOWLINE

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
☐ Dead floating crabs ☒ Withering of vegetation ☒ Others (Specify)

iii. Delineation of Impacted area

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m²)

- i.
ii.
iii.
iv.

(c) Creek/Creek lets

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs

☒ Video coverage

☒ Mapping

9. Samples taken.....

nta

10. Investigation carried out by

☒ Foot

☒ Boat

☒ Aircraft

11. Remarks/Recommendation

REPAIRS SHOULD BE CARRIED OUT ON
THE AFFECTED FLOWLINE AND SURVEILLANCE ACTIVITY
INCREASED IN THE AREA TO PREVENT A RE-OCCURENCE.

12. Time Investigation ended.....

2.45 p.m.

13. Name and Signature of Participants

❖ NOSDRA

1. R...