



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN PETROLEUM DEVELOPMENT COMPANY
OML 26 ASSET MANAGEMENT TEAM.

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....

3. Incident Details

- i. Date of Incident: 11 / 05 / 2019 ii. Date first reported: 12 / 05 / 2019
iii. Date of first investigation: 13 / 05 / 19 iv. Spill Incident No: NPDC/OML26/AMT/0519/003
v. Date of follow-up investigation: - / - / -
vi. Time investigation started: 2:10 PM
vii. Estimated quantity spilled(bbls): 2 bbls viii. Quantity Recovered: NONE

4. Site Details

- i. Site/Location: NPDC 10" OGWI-ERIEMU DELIVERY LINE @ ENLAGBIDH
ii. State: DELTA STATE iii. L.G.A: ISOKO NORTH
iv. Spill Co-Ordinates: N(m) 05° 33' 16.1"
E(m) 006° 11' 34.04"

v. Spill area

- ☐ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☒ Others (specify) SEASONAL SWAMP

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☒ Others (specify) NONE

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock

ii. Type of Oil contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)

iii. Facility

- ☐ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☒ Others (specify) DELIVERY LINE

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☒ Others (specify) 2" ILLEGAL HOP TAP VALVE ATTACHED AT 12'O'CLOCK POSITION TO THE OML 26 10" DELIVERY LINE.



6. Impact of Incident

i. Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing Net ☐ Makeshift
☐ Permanent ☒ Others VEGETATION

8. Extent of Impact

a) Community (indicate name)

- i. ENIAGBIDU
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
//	//	//	//

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
//	//	//	//

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
//	//	//	//

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
//	//	//	//

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken..... NONE

11. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

12. Remarks/Recommendation..... IMMEDIATE REPAIR, CLEAN-UP OF THE
IMPACTED AREA, CLEAR COMPANY ROW AND INTENSIFY
SURVEILLANCE ON THE ROW

13. Time investigation ended..... 4:45 PM