



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

*Note: This JIV form is to be completed and signed by all participating parties in the field*

1. Company: ATEO (AEEPCO/NCTW/2019/10)

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution  
☐ Others (Specify) .....

3. Incident Details

- i. Date of Incident: 5/5/2019 ii. Date first reported: .....  
iii. Date of first investigation: 7/5/2019  
iv. Date of follow-up investigation: .....  
v. Time investigation started: .....  
vi. Estimated quantity spilled: 336.8 Bbls

4. Site Details

- i. Site/Location: 30" NCTW + Boro  
ii. Position of Spill/Leak: 481180-494 ME 61649-78 MN

iii. Spill area

- ☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline  
☐ Near shore ☐ Offshore ☐ Others (Specify) .....

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) .....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock  
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products  
☐ Others (Specify) .....

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig  
☐ Storage Tank ☐ Compressor Plant  
☐ Others (Specify) .....

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident  
☐ Operational Error ☐ Others (Specify) .....

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid  
☐ Others (Specify) .....

## 6. Impact of Incident

### i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water  
☐ Venerable Objects ☐ Others (Specify) .....

### ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes  
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify) .....

### iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

## 7. Extent of Impact

### (a) Community (Indicate name)

- i. ....  
ii. ....  
iii. ....  
iv. ....

### (b) Land (Indicate area in m<sup>2</sup>)

- i. ....  
ii. ....  
iii. ....  
iv. ....

### (c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (d) Swamp

☒ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (e) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (f) Shoreline/water

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

8. Photograph/Map/Chart Ref.

☒ Still photographs    ☒ Video coverage    ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☐ Foot    ☒ Boat    ☐ Aircraft

11. Remarks/Recommendation. The spill resulted from the illegal activities of oil thieves. The surveillance should be improved upon.

12. Time Investigation ended.....