




*Note: This JIV Form is to be completed and signed by all participating parties in the field*

- vii. Estimated quantity spilled(bbls):..... viii. Quantity Recovered:.....

☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☒ Others (specify) none

☒ Others (specify). A Y-Shaped 2" Valve attached at 12 O'clock position on a 12" pipeline



## 6. Impact of Incident

### i. Properties impacted by the incident

- ☐ Farmland   ☐ Fish Pond   ☐ Vegetation   ☐ Fishing Net   ☐ Surface water  
☐ Venerable Objects   ☒ Others (specify) ... NONE

### ii. Nature of impact

- ☐ Oil stained vegetation   ☐ Oil stained fishing nets   ☐ Dead floating fishes  
☐ Dead floating crabs   ☐ Withering of vegetation   ☒ Others ... NONE

### iii. Delineation of impacted area

- ☒ Within Company's facility/ROW   ☐ Outside Company's facility/ROW

## 7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops   ☐ Fish Farm/ Pond   ☐ Fishing Net   ☐ Makeshift  
☐ Permanent   ☒ Others ... NONE

## 8. Extent of Impact

### a) Community (indicate name)

- i. ....  
 ii. ....  
 iii. ....  
 iv. ....

### b) Land (indicate area in m<sup>2</sup>)

- i. ....  
 ii. ....  
 iii. ....  
 iv. ....

### b) Creeks/Creek lets

☐ Tidal





☐ Non-tidal

| NAME                                                                                | DIRECTION OF SLICK                                                                  | LENGTH OF SLICK                                                                       | WIDTH OF SLICK                                                                        |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
|  |  |  |  |

### c) Swamp

☐ Tidal




☐ Non-tidal

| NAME                                                                                | DIRECTION OF SLICK                                                                  | LENGTH OF SLICK                                                                      | WIDTH OF SLICK                                                                        |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
|  |  |  |  |





### d) River

☐ Tidal

☐ Non-tidal

| NAME                                                                                | DIRECTION OF SLICK                                                                  | LENGTH OF SLICK                                                                      | WIDTH OF SLICK                                                                        |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
|  |  |  |  |

### e) Shoreline/water

| NAME                                                                                | DIRECTION OF SLICK                                                                  | LENGTH OF SLICK                                                                      | WIDTH OF SLICK                                                                        |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
|  |  |  |  |

9. Photograph/Map/Chart Ref.

☒ Still photographs   ☐ Video coverage   ☐ Mapping

10. Samples taken..... NONE

11. Investigation carried out by

☒ Foot   ☐ Boat   ☐ Aircraft

12. Remarks/Recommendation. Company should immediately repair the pipeline and also intensify surveillance around the area.

13. Time investigation ended 4:41 pm