



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY (NAOC)
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
i. Date of Incident: 29/05/2019 ii. Date first reported: 30/05/2019
iii. Date of first investigation: 04/06/2019 iv. Spill Incident No: 2019/NL/LAR/014/04
v. Date of follow-up investigation: -/-/-
vi. Time investigation started: 09:15AM
vii. Estimated quantity spilled(bbls): NILL viii. Quantity Recovered: NILL
4. Site Details
i. Site/Location: 10' IRR/KNWALE PIPELINE AT IBREBE
ii. State: DELTA iii. L.G.A: NDOKWA EAST
iv. Spill Co-Ordinates: N(m) 05° 35' 43.3"
E(m) 006° 26' 50.1"
v. Spill area
☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify) SEASONAL SWAMP
iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify) NON
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock NOT APPLICABLE
ii. Type of Oil contaminant
☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify) NOT APPLICABLE
iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify) NOT APPLICABLE
iv. Cause of Spill
☐ Corrosion ☐ Equipment Failure ☐ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify) NOT APPLICABLE
v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify) NOT APPLICABLE



NOTE: DURING INSPECTION, THE FOLLOWING WERE OBSERVED:

- (i) BEFORE EXCAVATION, THE SUSPECTED POINT WAS SUBMERGED WITH WATER WHICH WAS IN CONTRAST TO ITS IMMEDIATE ENVIRONS. THEREBY RAISING A SUSPICIOUS CONCERN:

6. Impact of Incident

i Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify).... NOT APPLICABLE

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others... NOT APPLICABLE

iii. Delineation of impacted area

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing Net ☐ Makeshift NOT APPLICABLE
☐ Permanent ☐ Others NOT APPLICABLE

8. Extent of Impact

a) Community (indicate name)

- i. NOT APPLICABLE
ii.
iii.
iv.

b) Land (indicate area in m²)

- i. NOT APPLICABLE
ii.
iii.
iv.

b) Creeks/Creek lets

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>N</u>	<u>N</u>	<u>N</u>	<u>N</u>

c) Swamp

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>N</u>	<u>N</u>	<u>N</u>	<u>N</u>

d) River

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>N</u>	<u>N</u>	<u>N</u>	<u>N</u>

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>N</u>	<u>N</u>	<u>N</u>	<u>N</u>

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken... NIL

11. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

12. Remarks/Recommendation ⁽ⁱ⁾ MAOR SHOULD INTENSIFY SURVEILLANCE,

(ii) HOUSE KEEPING OF THE AREA (ESPECIALLY RIGHT OF WAY)
IS HIGHLY IMPORTANT.

13. Time investigation ended... 3:40pm