



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**

**JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NPDC/FHN JV OML-26

2. Type of Complaint/Incident:

☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution

☐ Others (Specify).....

3. Incident Details

i. Date of Incident: 10/06/19 ii. Date first reported: 19/06/19

iii. Date of first investigation: 20/06/19 iv. Spill Incident No.: NPDC/OML26/AMT/HSE/067/06

v. Date of follow-up investigation: .....

vi. Time investigation started: 2:00 PM

vii. Estimated quantity spilled(bbls): 5 viii. Quantity Recovered: 2

4. Site Details

i. Site/Location: 16" Pipeline along Ozoro-Owhelgbo road

ii. State: DELTA iii. L.G.A: ISOKO NORTH

iv. Spill Co-Ordinates: N(m) 05° 33' 37.7"  
E(m) 006° 13' 25.6"

v. Spill area

☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline

☐ Near shore ☐ Offshore ☐ Others (specify).....

vi. Structural Controls in Place

☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☒ Others (specify) NIL

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☒ 3 O' Clock  
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock

ii. Type of Oil contaminant

☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products  
☐ Others (specify) .....

iii. Facility

☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig  
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....

iv. Cause of Spill

☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident  
☐ Operational Error ☐ Others (specify).....

v. Visible Sign of Third Party Interference

☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid

☒ Others (specify) Casted portion @ the 16" pipeline by CCC Construction Company





## 6. Impact of Incident

### i. Properties impacted by the incident

- ☐ Farmland   ☐ Fish Pond   ☒ Vegetation   ☒ Fishing Net   ☒ Surface water  
☐ Venerable Objects   ☐ Others (specify).....

### ii. Nature of impact

- ☒ Oil stained vegetation   ☒ Oil stained fishing nets   ☐ Dead floating fishes  
☐ Dead floating crabs   ☒ Withering of vegetation   ☐ Others.....

### iii. Delineation of impacted area

- ☒ Within Company's facility/ROW   ☒ Outside Company's facility/ROW

## 7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops   ☒ Fish Farm/ Pond   ☒ Fishing Net   ☐ Makeshift  
☐ Permanent   ☐ Others .....

## 8. Extent of Impact

### a) Community (indicate name)

- i. Zero (emese)  
 ii. ....  
 iii. ....  
 iv. ....

### b) Land (indicate area in m<sup>2</sup>)

- i. ....  
 ii. ....  
 iii. ....  
 iv. ....

### b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### c) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### d) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### e) Shoreline/water

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |



9. Photograph/Map/Chart Ref.

☒ Still photographs    ☐ Video coverage    ☐ Mapping

10. Samples taken..... NIL

11. Investigation carried out by

☒ Foot    ☐ Boat    ☐ Aircraft

12. Remarks/Recommendation..... NPDC/FAN SHOULD DO AN IMMEDIATE  
REPAIR ~~AND~~ ~~CLEAN UP~~ OF THE AFFECTED PORTION AND  
CLEAN-UP OF IMPACTED ENVIRONMENT