

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company **NIGERIAN AGIP OIL COMPANY [NAOC]**

2. Type of Complaint/Incident:

☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution

☒ Others (Specify) _____

3. Incident Details

i. Date of Incident: **27/07/2018** ii. Date first reported: **27/07/2018**

iii. Date of first investigation: **31/07/2018** iv. Spill Incident No: **2018/LAR/101/128**

v. Date of follow-up investigation: _____

vi. Time investigation started: **11:20 HRS**

vii. Estimated quantity spilled (bbls): **0.81** viii. Quantity Recovered: **NIL**

4. Site Details

i. Site/Location: **TAYLOR CREEK 2SS F/L AT KALABA/AYAMABELE/AKUMBAI**

ii. State: **BAYELSA** iii. L.G.A: **YENAGOA**

iv. Spill Co-Ordinates N(m): **05° 07' 43.9"**
E(m): **006° 27' 23.1"**

v. Spill area

☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline

☒ Near shore ☒ Offshore ☒ Others (specify) _____

iv. Structural Controls in Place

☐ Boom ☐ Trenches ☐ Band wall ☐ Sorbents ☐ Others (specify) _____

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock

☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock

ii. Type of Oil contaminant

☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined products

☒ Others (specify) _____

iii. Facility

☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig

☒ Storage Tank ☒ Compressor Plant ☒ Others (specify) _____

iv. Cause of Spill


☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident

☒ Operational Error ☒ Others (specify) _____

v. Visible Sign of Third Party Interference

☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid

☒ Others (specify) _____



6. Impact of Incident

i. Properties impacted by the incident

☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☒ Others (specify) _____

ii. Nature of impact

☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
☒ Dead floating crabs ☒ Withering of vegetation ☒ Others _____

iii. Delineation of impacted area

☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

☒ Crops ☒ Fish Farm/ Pond ☒ Fishing Net ☒ Makeshift
☒ Permanent ☒ Others _____

8. Extent of Impact

a) Community (indicate name)

i. _____
 ii. _____
 iii. _____
 iv. _____

b) Land (indicate area in m^2)

i. 63.380
 ii. _____
 iii. _____
 iv. _____

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
		N/A	

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
		N/A	

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
		N/A	

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
		N/A	

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken..... *N/A*

11. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation *SURVEILLANCE ~~ON~~ THE FACILITY/
SHOULD BE INTENSIFIED.*

13. Time investigation ended *13:31 HRS*

14. Name and Signature of Participants