



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY LTD (NADO)

2. Type of Complaint/Incident:

☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution

☐ Others (Specify).....

3. Incident Details

i. Date of Incident: 22 / 10 / 19 ii. Date first reported: 22 / 10 / 19

iii. Date of first investigation: 23 / 10 / 19 iv. Spill Incident No:.....

v. Date of follow-up investigation: 24 / 10 / 2019

vi. Time investigation started:.....

vii. Estimated quantity spilled(bbls):..... viii. Quantity Recovered:.....

4. Site Details

i. Site/Location: 14" OGBORBIRI / TEB-DABA PIPELINE AT OPA

ii. State: BAYELSA iii. L.G.A: SOUTHERN LTAN ORPESUMA

iv. Spill Co-Ordinates: N(m) 04 49' 08.6"
E(m) 005 38' 34.5"

v. Spill area

☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline

☒ Near shore ☒ Offshore ☒ Others (specify).....

iv. Structural Controls in Place

☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock

☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock

ii. Type of Oil contaminant

☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products

☒ Others (specify).....

iii. Facility

☐ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig

☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....

iv. Cause of Spill

☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident

☒ Operational Error ☒ Others (specify).....

v. Visible Sign of Third Party Interference

☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid

☒ Others (specify).....

6. Impact of Incident

i. Properties impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
☒ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
☒ Dead floating crabs
☒ Withering of vegetation
☒ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW
☐ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops
☐ Fish Farm/ Pond
☐ Fishing Net
☐ Makeshift
☐ Permanent
☐ Others

8. Extent of Impact

a) Community (indicate name)

- i. OKPOTUWARI
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i. 1822.28m²
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken..... *- NIL -*

11. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation..... *SITE REQUIRES IMMEDIATE
CLEANUP. NADC SHOULD IMPROVE ON SURVEILLANCE
OF ITS ASSETS.*

13. Time investigation ended.....