



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV Form is to be completed and signed by all participating parties in the field

NPDC/NDW/OML 34

1. Company:
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
i. Date of Incident: 28 OCTOBER 2019 ii. Date first reported: 28 OCTOBER 2019
iii. Date of first investigation: 29 OCTOBER 2019 iv. Spill Incident No: NPDC/NDW/HSE/10/2019
v. Date of follow-up investigation:
vi. Time investigation started: 1:25pm
vii. Estimated quantity spilled(bbls): 80 BBL viii. Quantity Recovered:
4. Site Details
i. Site/Location: 10" UTOROGU/UPS DELIVERY LINE @ UGHEVWUGHE
ii. State: DELTA iii. L.G.A: UGHELI SOUTH
iv. Spill Co-Ordinates: N(m) 05° 29' 33.4"
E(m) 005° 55' 01.9"

v. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☒ Others (specify) SEASONAL SWAMP

iv. Structural Controls in Place

- ☐ Boom ☐ Frenches ☐ Bund wall ☐ Sorbents ☐ Others (specify) NONE

Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock

ii. Type of Oil contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)

iii. Facility

- ☐ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify) DELIVERY LINE

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☒ Others (specify) 3" BALL VALVE WAS OBSERVED TO BE ATTACHED @ THE LINE



6. Impact of Incident

i. Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☒ Surface water
☐ Venerable Objects ☒ Others (specify) SOIL

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☒ Withering of vegetation ☒ Others SOIL

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing Net ☐ Makeshift
☐ Permanent ☐ Others

8. Extent of Impact

a) Community (indicate name)

- i. Ughevughe
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>[Signature]</u>	<u>[Signature]</u>	<u>[Signature]</u>	<u>[Signature]</u>

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>[Signature]</u>	<u>[Signature]</u>	<u>[Signature]</u>	<u>[Signature]</u>

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>[Signature]</u>	<u>[Signature]</u>	<u>[Signature]</u>	<u>[Signature]</u>

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>[Signature]</u>	<u>[Signature]</u>	<u>[Signature]</u>	<u>[Signature]</u>



9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

0. Samples taken... NONE

1 Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

2. Remarks/Recommendation ⁽¹⁾ THE COMPANY SHOULD IMMEDIATELY RECOVER

THE FREE PHASE OIL (2) THEY SHOULD CLEAN UP THE ENVIRONMENT AND TO

BE MONITORED BY THE AGENCY (3) THEY SHOULD ALSO DO REPAIR OF
DAMAGED FACILITY.

Time investigation ended 5:30 PM