

2019 / LAZ / 144 /



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NADC
2. Type of Complaint/Incident:  
☒ Oil Pollution    ☒ Fire/Explosion    ☒ Drilling Mud/Chemical Pollution  
☒ Others (Specify) .....
3. Incident Details  
i. Date of Incident: 25<sup>th</sup> DEC 2019    ii. Date first reported: 26<sup>th</sup> DEC 2019  
iii. Date of first investigation: 26<sup>th</sup> DEC 2019  
iv. Date of follow-up investigation: N/A  
v. Time investigation started: 1650 HRS  
vi. Estimated quantity spilled: 6-5 BBLs
4. Site Details  
i. Site/Location: EBOCHA TT FLOWLINE, ALONG OLD EBOCHA FERRY ROAD  
ii. Position of Spill/Leak: NGBEDE N05° 27' 04.2", E006° 41' 01.2"  
iii. Spill area  
☒ Land    ☒ Swamp    ☒ Freshwater    ☒ Mangrove    ☒ Coastline  
☒ Near shore    ☒ Offshore    ☒ Others (Specify) .....  
iv. Structural Controls in Place  
☒ Boom    ☒ Trenches    ☒ Bund Wall    ☒ Sorbents    ☒ Others (Specify) .....
5. Circumstances Around Spill Point  
i. Visual observation of Hole Position  
☒ 12 0'Clock    ☒ 10 0'Clock    ☒ 2 0'Clock    ☒ 3 0'Clock  
☒ 4 0'Clock    ☒ 5 0'Clock    ☒ 6 0'Clock / 2-2 O'clock  
ii. Type of Oil Contaminant  
☒ Crude Oil    ☒ Condensate    ☒ Chemicals    ☒ Refined Products  
☒ Others (Specify) .....  
iii. Facility  
☒ Pipeline    ☒ Flow Line    ☒ Wellhead    ☒ Manifold    ☒ Flow Station    ☐ Rig  
☒ Storage Tank    ☒ Compressor Plant  
☒ Others (Specify) .....  
iv. Cause of Spill  
☒ Corrosion    ☒ Equipment Failure    ☒ Third Party Interference    ☒ Accident  
☒ Operational Error    ☒ Others (Specify) .....  
v. Visible Sign of Third Party Interference  
☒ Hacksaw Marks    ☒ Drilled Holes    ☒ Blasting    ☒ Theft    ☒ Acid  
☒ Others (Specify) .....

## 6. Impact of Incident

### i. Properties Impacted by the incident

- ☒ Farmland  
 ☒ Fish Pond  
 ☒ Vegetation  
 ☒ Fishing Net  
 ☒ Surface water  
☒ Venerable Objects  
 ☒ Others (Specify) .....

### ii. Nature of impact

- ☒ Oil stained vegetation  
 ☒ Oil stained fishing nets  
 ☒ Dead floating fishes  
☒ Dead floating crabs  
 ☒ Withering of vegetation  
 ☒ Others (Specify) .....

### iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW  
 ☒ Outside Company's facility/ROW

## 7. Extent of Impact

### (a) Community (Indicate name)

i. MGBEDE

ii. ....

iii. ....

iv. ....

### (b) Land (Indicate area in m<sup>2</sup>)

i. 1,500 : 26

ii. ....

iii. ....

iv. ....

### (c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      | <u>ASTA</u>        |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (d) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      | <u>ASTA</u>        |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (e) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      | <u>ASTA</u>        |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (f) Shoreline/water

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      | <u>ASTA</u>        |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken... AS/A .....

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation. IMMEDIATE CLEAN-UP OF CRUDE OIL IMPACTED AREA

IMPROVE SURVEILLANCE ALONG THE FLOWLINE

DELIMITATION SURVEY OF IMPACTED AREA WAS CARRIED OUT

12. Time Investigation ended... 17/01/2025 .....