

4 COMMUNITY

1. Police OLA Joseph Abaitono (Chief)
2. Goble & Harold Abaitono (Community)
3. Hilobido Nosa Toga (Kaga Community)
09/05/20

5 COMPANY

1. Harrison Akwasi 09-5-2020

6 STATE MINISTRY OF ENVIRONMENT

1. EXHIBITOR EUNICE [EBO]

7 DPA

1. Michael - 09/05/20

8 NIOSHA

1. Akwasi, POTIM Daniel 09/05/20

14. Name and Signature of Participants

13. Time investigation ended

03:30 PM

12. Remarks/Recommendation
CARRY OUT IMMEDIATE SURVEILLANCE
HECK AND IDENTIFY SURVIVORS

11. Investigation carried out by
Edson Edson
IMMEDIATE RETURN OF THE DAMAGED
IMMEDIATE CLOSURE OF THE INCIDENT

10. Samples taken

NONE

9. Photograph/Map/Chart/Plot
☐ Still photographs ☐ Video coverage ☐ Mapping

--	--	--	--	--	--

☐ Others (specify)

6. Impact of Incident

i. Properties impacted by the incident

☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☒ Surface water

☐ Venerable Objects ☐ Others (specify)

ii. Nature of impact

☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes

☐ Dead floating crabs ☐ Withering of vegetation ☐ Others

iii. Delimitation of impacted area

☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

☐ Crops ☐ Fish Farm/ Pond ☐ Fishing Net ☐ Makeshift

☐ Permanent ☐ Others

8. Extent of Impact

a) Community (indicate name)

b) Land (indicate area in m²)



b) Creeks/Creek Iets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Name: This JIV Form is to be completed and signed by all participating parties in the field
ENGAGEED RESOURCE LIMITED

RESPONSE AGENCY WAREHOUSE
ISSUED
3.1.2020
SIGN: [Signature]
DATE: 3.1.2020

Company: **ENGAGEED RESOURCE LIMITED**

Type of Complaint/Incident: ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution

Others (Specify): ☐ **Oil Pollution**

Incident Details: **06/05/2020** Date first reported: **07/05/2020**

i. Date of Incident: **06/05/2020** iv. Spill Incident No: **01/MIA8/HSE/NO5/2020/015**

iii. Date of first investigation: **07/05/2020** vi. Quantity Recovered: **NIL**

v. Date of follow-up investigation: **11/05/2020**

vi. Time investigation started: **6** vii. Estimated quantity spilled (bbls): **NIL**

viii. Site Details: **6" EXPORT LINE BETWEEN TP7 & TP8 AT NODRA**

i. Site Location: **6" EXPORT LINE BETWEEN TP7 & TP8 AT NODRA**

ii. State: **EDO** iii. L.G.A.: **IKPOBA - OKHA**

iv. Spill Co-Ordinates: N(m): **06° 53' 36"** E(m): **005° 30' 36.5"**

v. Spill area: ☒ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline

☐ Near shore ☐ Offshore ☐ Others (specify): **NONE**

iv. Structural Controls in Place: ☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify): **NONE**

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock

☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock

ii. Type of Oil contaminant

☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products

☐ Others (specify): **NONE**

iii. Facility

☐ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig

☐ Storage Tank ☐ Compressor Plant ☐ Others (specify): **EXPORT LINE**

iv. Cause of Spill

☐ Corrosion ☐ Equipment Failure ☐ Third Party Interference ☐ Accident

☐ Operational Error ☐ Others (specify): **ASSET DAMAGE**

v. Visible Signs of Third Party Interference

☐ Backsaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid