



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

*Note: This JIV form is to be completed and signed by all participating parties in the field*

1. Company: SPDC

2. Type of Complaint/Incident:

- ☐ Oil Pollution      ☐ Fire/Explosion      ☐ Drilling Mud/Chemical Pollution  
☐ Others (Specify) THEFT POINT INSTALLATION

3. Incident Details

- i. Date of Incident: ..... ii. Date first reported: 5/2/20/20  
iii. Date of first investigation: .....  
iv. Date of follow-up investigation: 6/5/2020  
v. Time investigation started: 12.30 PM  
vi. Estimated quantity spilled: NIL

4. Site Details

- i. Site/Location: 14" OTCORDA/RUMUOKPB TL @ EDOBOKTA  
ii. Position of Spill/Leak: N05° 01' 24.9", E006° 37' 21.3"  
iii. Spill area N05° 01' 25.0", E006° 37' 21.1"  
☒ Land      ☐ Swamp      ☐ Freshwater      ☐ Mangrove      ☐ Coastline  
☐ Near shore      ☐ Offshore      ☐ Others (Specify) .....  
iv. Structural Controls in Place  
☐ Boom      ☐ Trenches      ☐ Bund Wall      ☐ Sorbents      ☐ Others (Specify) NA

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 O'Clock      ☐ 10 O'Clock      ☐ 2 O'Clock      ☐ 3 O'Clock  
☐ 4 O'Clock      ☐ 5 O'Clock      ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☐ Crude Oil      ☐ Condensate      ☐ Chemicals      ☐ Refined Products  
☐ Others (Specify) NON LEAK POINT

iii. Facility

- ☒ Pipeline      ☐ Flow Line      ☐ Wellhead      ☐ Manifold      ☐ Flow Station      ☐ Rig  
☐ Storage Tank      ☐ Compressor Plant  
☐ Others (Specify) .....

iv. Cause of Spill

- ☐ Corrosion      ☐ Equipment Failure      ☐ Third Party Interference      ☐ Accident  
☐ Operational Error      ☐ Others (Specify) NA

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks      ☐ Drilled Holes      ☐ Blasting      ☒ Theft      ☐ Acid  
☐ Others (Specify) VALVE INSTALLATION



## 6. Impact of Incident

### i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water  
☐ Venerable Objects ☐ Others (Specify) ..... NA .....

### ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes  
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify) ..... NA .....

### iii. Delineation of Impacted area

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW NA

## 7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m<sup>2</sup>)

- i. .... BD BOKA ..... i. .... NIL .....  
ii. .... ii. ....  
iii. .... iii. ....  
iv. .... iv. ....

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(d) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(e) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

8. Photograph/Map/Chart Ref.

☒ Still photographs    ☐ Video coverage    ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot    ☐ Boat    ☐ Aircraft

11. Remarks/Recommendation..... SECURITY SHOULD BE  
BOOED UP ON THE ROW TO CHECK  
THE ACTIVITIES OF ILLEGAL BUNKERS

12. Time Investigation ended..... 3.45 PM

13. Name and Signature of Participants