



National Oil Spill Detection & Response Agency

FORM B

RISK BASED ASSESSMENT OF OIL SPILL INCIDENCE (RBA)

Note: This report must be submitted within 2 weeks of spill incidence

1. GENERAL INFORMATION:			
i. Company Name:		Mobil Producing Nigeria Unlimited	
ii. Date of Assessment:		June 24, 2020	
iii. Incident Details:		Date of Incident	Date spill was stopped
iii a. Spill reference No: 001/2020		June 19, 2020 / 11:19 hours local time	June 19, 2020 / 11:19 hours local time
		Method Used ☐ Clamping ☐ Well Shut-in ☐ Valve Shut-in ☐ F/Station Shut down ☒ Others: Decanting operation was immediately discontinued and the area cordoned off	
iv. Estimated quantity spilled: 0.000002 bbls of diesel			
v. Estimated quantity recovered: Nil			
vi. Cause of Spill ☐ Corrosion: ☐ Equipment Failure ☐ Third Party Interference ☐ Accident ☐ Operational ☒ Others:			
2. Site Details			
i. Site Name: Mobil Annex Lagos Fuel Tank Farm			
ii. GPS FIELD POINTS Total Length 1.2m Width 0.7m Differential GPS Yes/No Spill Start Point GPS: EASTINGS NORTHINGS Spill End Point GPS: EASTINGS NORTHINGS			
iii. Site area ☐ Land Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline ☐ Near Shore ☐ Offshore ☒ Others (sandy graveled area)			
iv. Facility ☐ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig ☐ Storage Tank ☐ Compressor Plant Others: ☒ seepage during decanting operations			
v. Site Characterization a. Sea Conditions ☐ Wind Direction: ☐ Low Tide ☐ High Tide ☐ Calm ☐ Rough ☐ Swell Height: ☐ Current direction: b. Weather Conditions ☐ Bright and Sunny ☐ Slight rain Temperature Wind Speed: ☒ Others: Clear			

vi. Visual Observation of impacted area:

- (i) Any oil sheen on water
- (ii) Any oil sheen on water
- (iii) Any oil sheen on water
- (iv) Any oil sheen on water
- (v) Any oil sheen on water

Yes ☐ No ☐ N/A ☒

Yes ☐ No ☐ N/A ☐

Yes ☐ No ☐ N/A ☐

Yes ☐ No ☐ N/A ☐

Yes ☐ No ☐ N/A ☐

Receptor Assessment

Receptor	Pathway to Impacted Area(m ²)	Distance to Impacted Area(m ²)	Estimated Area of Impact Area(m ²)	Receptor Impacted (Yes/No)	Remarks
Farmland					
Fish Pond					
Vegetation					
Surface Water					
Venerable Object					
Human Habitation					
Livestock					
Plantation					
Swamp					

vii. Any Casualties☐ Yes☒ No

If yes, give details

viii. Clean-up Program details – Not Applicable

a. Method of clean-up :

b. Time frame for clean-up

ix. General Remarks: -**REPORTING OFFICER:****Abiodun Lansebe****DESIGNATION:****Manager, Fuel Operations**

DocuSigned by:

SIGNATURE:*Lansebe Abiodun***DATE:**

June 30, 2020

**Clean-up program report must be submitted within 2 weeks of spill incidence.*